

Date: Tuesday, 1/31/2006 1:11:47 PM
 User: Kim Johnston

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: SKIDTUBE
Job Number	: 25691		
Estimate Number	: 11545	Part Number	: D204635011
P.O. Number	: N/A	Drawing Number	: N/A
This Issue	: 1/31/2006	Project Number	: N/A
Prsht Rev.	: NC	Drawing Revision	: N/A
First Issue	: N/A	Material	: N/A
Previous Run	: 25690	Due Date	: 2/20/2006
Written By	: <u>See Comment Below</u>	Qty:	1
Checked & Approved By	: <u>JA 06.01.31</u>	Um:	Each
Comment	: Est Rev:G-02.08.28 Removed QC5 KJ		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description:
----------------	------------------------------	---------------------

1.0

DC

DOCUMENT CONTROL

**Comment:** DOCUMENT CONTROL

Photocopy bluefile and Type labels as per PPP D204-635-011 CHG004

K 06/02/23 (1)

2.0

25691A

SKIDTUBE

**Comment:** Sub-Component Pick:

Qty	Part Number	Description	Batch
1	D204-635-041	Skidtube Assembly	B25691A

3.0

PACKAGING 1

PACKAGING RESOURCE #1

**Comment:** PACKAGING RESOURCE #1

Pick Packing Kit

4.0

K10003

D205-634-011 Saddle Kit

**Comment:** Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
1	K10003	Saddle Kit	B25804

K 6/6/02 (1)

5.0

QC4

INSPECT 100% KITS FOR COMPLETENESS

**Comment:** INSPECT 100% KITS FOR COMPLETENESS

K 06/06/02

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: DB Date: 06/04/05
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date				

NOTE: Date & initial all entries

Date: Tuesday, 1/31/2006 1:11:47 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SKIDTUBE

Job Number: 25691

Part Number: D204635011

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D204-635-011

Location: F621

PPP Rev: B

1646/2 (1)

7.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

Inspection Level 21

120606/05 (1)

Job Completion



12060605

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date				

NOTE: Date & initial all entries

Process Sheet

Additional Product	

Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

...the ...

Batch: 828029

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. The second step is to define the objectives and goals of the project. This involves determining what you want to achieve and how you will measure success.

3. The third step is to develop a plan of action. This involves identifying the steps that need to be taken to achieve the objectives and goals.

4. The fourth step is to implement the plan. This involves putting the plan into action and monitoring progress.

5. The fifth step is to evaluate the results. This involves assessing the outcomes of the project and determining whether the objectives and goals have been achieved.

6. The sixth step is to report on the results. This involves communicating the findings of the project to the relevant stakeholders.

7. The seventh step is to reflect on the process. This involves thinking about what worked well and what could be improved for future projects.

8. The eighth step is to share the results. This involves making the findings of the project available to others who may be interested.

9. The ninth step is to celebrate success. This involves acknowledging the achievements of the team and celebrating the successful completion of the project.

10. The tenth step is to learn from the experience. This involves reflecting on the project and identifying lessons learned that can be applied to future projects.

16

Batch: B25952

Batch: 62,328

Batch: 626310

Batch: B25592

Batch: B-26335

Batch: 62686

Batch: B 26320

Batch: B26331

Batch: 626330

Batch: 526333

Batch: 526334

Batch: B25818

Batch: B25819

Batch: 25690

Batch: 95691

Batch: 2334

25333

Update all kits K10003 With Dsi9344 & dsi9180 Paperwork

Batch: B26358x3

Batch: B26848 x2

Batch: _____

634
-01

34
41-7 25817

011 B21821-635-041
~~B20000-635-041~~
 B1848-635-041
 B21564-635-041

31

2
06/07/27